## MONTGOMERY COUNTY COMBINED GENERAL HEALTH DISTRICT

451 WEST THIRD STREET

AYTON, OHIO 45401

May 24, 1978

RECEIVED

MAY 2 6 1978

Mr. Alcine S. Grillot South Dayton Landfill 2708 Kreitzer Road Dayton, Ohio 45439

South Dayton Landfill, 1975 Springboro Road, Dayton, Ohio 45439

Dear Mr. Grillot:

Representatives from this office and the Ohio Environmental Protection Agency visited your licensed landfill operation located at 1975 Springboro Road on May 11, 1978 for the purpose of conducting a general inspection. At that time we found that the conditions of our letter dated June 16, 1976 have not been followed as required, and we also found that a nuisance condition exists. The problems are as follows:

Moroine Recycling

- 1. That on-site compacting and area filling with dirt, concrete, and asphalt has not been conducted satisfactorily; and,
- 2. That we could find no area that had been filled and covered with at least two (2) feet of soil that would support vegetation; and,
- That containers labelled as hazardous are on the premises with some of the contents still in them.

Based upon these findings, we must notify you to eliminate these stated nuisance conditions by:

- 1. Compacting and covering all materials on the site that are considered to be waste (excluding salvage materials) and provide at least two (2) feet of final cover that will support vegetation.
- 2. Do not accept drums or plastic containers that are labelled as "Hazardous" unless the containers have been washed and the hazardous materials removed prior to acceptance at your landfill. Hazardous materials can only be deposited on sites that are licensed to accept them. Remove all hazardous containers from the premises for washing and/or other disposal. Do not bury these containers on your site prior to washing.







cc: Joe Moore, OERA

Mr. Alcine S. Grillot